

EAST Search History

EAST Search History (Interference)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L5	1	weld\$3 and ignit\$3 and ((adjust\$3 or control\$4) with parameter) and (control\$4 near device) and current and ((weld\$3 near process) with ((high near energy) and (low near energy)))	US-PGPUB; USPAT	ADJ	ON	2011/10/21 15:26
L6	1	weld\$3 and (ignit\$3 or start\$3) and ((adjust\$3 or control\$4) with (parameter or current or voltage)) and (control\$4 near device) and current and ((weld\$3 near process) with ((high near energy) and (low near energy)))	US-PGPUB; USPAT	ADJ	ON	2011/10/21 15:26
L7	1	weld\$3 and (ignit\$3 or start\$3) and ((adjust\$3 or control\$4) with (parameter or current or voltage)) and (control\$4 near device) and current and ((weld\$3 near process) with ((high near energy) and (low near energy))) and ((mov\$3 or retract\$3 or advanc\$3) with (wire or electrode))	US-PGPUB; USPAT	ADJ	ON	2011/10/21 15:26
L14	1	weld\$3 and ignit\$3 and ((adjust\$3 or control\$4) with parameter) and (control\$4 near device) and current and (weld\$3 near process) and (high near energy) and (low near energy) and (material with transition) and ((mov\$3 or retract\$3 or advanc\$3 or revers\$3) with (wire or electrode)) and ((electrode or wire) with convey\$4)	US-PGPUB; USPAT	ADJ	ON	2011/10/21 16:02

10/21/2011 4:08:01 PM

C:\Documents and Settings\hnguyen45\My Documents\EAST\Workspaces\10574401.wsp